

A

absolute locations 5:18
adiabatic 3:8, 5:34, 5:36–5:37, 6:1–6:3, 6:6, 8:32
adjacent polygon 5:46, 6:2, 6:8, 6:12
assembly drawings 5:6
assign materials 4:1, 5:1, 5:12, 5:29, 5:39, 5:50, 8:5
autoconvert 5:1–5:6, 5:11, 5:29, 8:1, 8:3–8:4, 8:7
AutoLISP programs 5:6
average temperature 5:8, 7:6, 7:15–7:17

B

background calc 7:3–7:4
bad points 6:9–6:11, 7:8
bitmap file 1:3, 3:1, 5:1–5:2, 8:4
blocking surfaces 5:37, 6:16–6:17
boundary conditions 1:1, 1:3, 3:8, 3:11–3:12, 4:1, 4:4,
5:1, 5:11, 5:19, 5:29, 5:33, 5:45–5:46, 5:48–5:50,
0:1–6:6, 6:8–6:19, 7:1, 7:8, 8:1, 8:31–8:34
boundary segment 3:8–3:9, 6:4, 6:6, 8:32, 8:34

C

calc manager 4:4, 7:2–7:3
calculation options 7:3, 7:6, 7:9, 7:12, 7:18
Calculation/Display Options 3:9, 7:10, 7:14, 7:17, 8:36
Calculation/Show U-factor 3:9, 7:5
cavities 1:1–1:3, 3:10, 5:1, 5:15, 5:32–5:38, 5:40–5:41,
5:44–5:46, 5:48–5:49, 5:51, 6:1, 6:15, 7:15, 8:30
cavity height 3:5
cavity model 3:10, 5:38, 5:40, 5:44–5:45, 5:48, 6:15–
6:16, 7:16
CI Model 5:30, 5:33, 5:35, 7:6
closed polylines 5:1, 5:3, 5:5–5:6
color flux magnitude results 7:17, 7:22
component library 5:31–5:32, 5:50
Condensation Index Model 3:1, 3:5, 3:10, 5:1, 5:34–
5:36, 7:6, 7:10
conductivity 5:1, 5:34, 5:36, 5:38, 5:40, 5:43, 5:45–
5:46, 7:15, 8:27
constant heat flux magnitude 3:1, 3:5, 3:10, 5:1, 5:34–
5:36, 7:6, 7:10
convergence 7:1, 7:5–7:6, 7:10, 7:12
convergence tolerance 7:6
copy 1:2–1:3, 2:6, 3:2, 3:6–3:7, 5:31, 5:50, 8:27, 8:29
cursor feedback bar 4:2
cursor position 4:2, 5:10, 7:15, 8:15, 8:20–8:21

D

detailed radiation model 3:10, 5:34, 5:37, 5:45, 6:15,
7:6, 7:10
display options 3:9, 7:1–7:2, 7:7, 7:10, 7:14, 7:17–7:18,
8:36
draw polygon 3:1, 3:11, 4:2, 5:12–5:13, 8:9–8:10, 8:12,
8:14–8:15
draw rectangle 3:1, 3:11, 5:12, 8:19–8:20, 8:24
draw repeat mode 5:12
draw spacer 3:5, 5:31–5:32, 8:23
Draw/Edit Points 5:21, 5:24, 6:10
Draw/Flip 3:7
Draw/Insert Point 5:23
Draw/Locator 3:5–3:7, 4:2, 5:20, 5:29, 8:28–8:29
Draw/Move 5:20
drawing area 4:2, 4:5, 5:4, 5:9, 5:17, 5:19, 5:24, 7:15,
8:2, 8:5, 8:9, 8:12, 8:15
drawing features 1:2, 3:2, 3:6, 5:7, 5:11–5:12, 5:24
drawing preferences 5:7
DXF File 1:1, 1:3, 3:1, 5:1–5:7, 5:9, 5:10–5:11, 5:13,
5:16, 5:29, 8:1, 8:3–8:5, 8:7–8:10
DXF file conversion 5:6, 5:11
DXF filter 5:1, 5:4

E

Edit/Copy 3:6–3:7, 8:29
Edit/Paste 3:6–3:7, 8:29
Edit/Select All 3:6–3:7, 5:50, 8:28–8:29
Edit/Undo 5:8, 5:21, 5:24
editing of IG polygons 5:8, 5:33
effective conductivity 5:1, 5:34, 5:36, 5:38, 5:40, 5:45–
5:46, 7:15, 8:27
emissivity 5:34, 5:36, 5:40, 5:43, 5:45–5:46, 6:16–6:17
error estimator 1:3, 7:4–7:5, 7:8, 7:10, 7:12, 7:18
export a THERM file 7:26
external radiation enclosure 3:4, 3:10, 5:41–5:42, 5:46–
5:48, 6:14–6:15, 6:17–6:18, 7:10

F

File/Export 7:26
finite element mesh 7:11, 7:15, 7:18, 7:20
flip 3:2, 3:6–3:7, 5:6, 5:24–5:25, 5:31, 6:5
flux vectors 1:1, 7:10–7:11, 7:20, 7:22
frame cavities 3:2, 3:4, 3:10, 5:38, 5:41, 5:44–5:46,
5:48, 6:15–6:16, 7:10, 7:16, 8:30

G

glazing cavity 3:10, 5:1, 5:34, 5:36–5:38, 5:41, 5:46
glazing system library 3:5, 5:29–5:30, 5:35–5:37, 8:21
glzsys.w4 3:5, 5:29–5:30, 8:23
graphic results 3:9, 7:11, 7:17–7:22
greenhouse window 3:10

H

heat flux 5:41, 5:46, 6:6, 6:14, 7:5, 7:7, 7:20, 7:22

I

insert points 3:3, 4:4, 8:19–8:20
inserting a glazing system 3:10, 5:29
isotherms 1:1, 1:4, 3:9, 7:1, 7:10–7:11, 7:19, 8:35

L

locator 3:5–3:7, 4:2, 5:20, 5:29, 5:33, 5:37, 5:50, 8:22,
8:24, 8:28–8:29

M

main menu 4:1–4:3
material library 3:4, 3:12, 5:1, 5:38–5:46, 5:48, 6:16,
8:10, 8:15, 8:30
material.lib 5:42, 5:49
mesh generator 1:3, 5:11, 6:8, 7:1, 7:9
mesh parameter 7:4, 7:9–7:10, 7:18
message bar 4:2
min/max temperatures 7:14
multiple boundary segments 6:3, 8:33

N

numeric cursor positioning 5:7, 5:17
Nusselt number 5:40, 5:46

O

origin 3:11, 4:2–4:3, 5:4, 5:9–5:10, 5:17, 8:5, 8:9, 8:14–
8:16
overlapping regions 5:7, 5:11, 5:23, 6:2, 6:12
overlaps 3:2, 5:3, 5:6, 5:7, 5:11, 5:14, 5:20, 6:1, 6:8,
6:12

P

paste 1:3, 3:2, 3:5–3:7, 5:6, 5:20, 5:31–5:32, 5:50, 8:27,
8:29
percent error energy norm 7:5–7:6, 7:12, 7:18
polygons 1:1, 3:2, 3:4, 3:6–3:7, 5:1, 5:3–5:9, 5:10–5:15,
5:17–5:21, 5:27–5:29, 5:33, 5:37–5:39, 5:45–5:48,
5:50, 6:1–6:2, 6:8–6:10, 7:8, 7:16, 8:3–8:10, 8:12,
8:15, 8:16, 8:19, 8:28–8:29, 8:30

polylines 5:1–5:6

pull-down list 3:1, 3:5, 4:4, 5:30, 5:38, 5:40–5:41, 5:47,
6:4, 6:6, 6:12–6:14, 7:12, 7:24, 7:26, 8:5, 8:10,
8:12, 8:15, 8:23–8:24

Q

Quad Tree Mesh Parameter 7:9–7:10

R

radiation model 1:2–1:3, 3:10, 5:34, 5:37, 5:41, 5:44–
5:46, 6:15, 7:6, 7:10
Radiation Surface 5:48, 6:17
rectangles 3:2, 5:1, 5:15, 5:18, 5:32, 5:50

S

scrolling 5:10, 7:26, 8:15
select multiple boundary segments 6:3, 8:33
select special 5:19–5:20, 5:40
select the material 3:1–3:2, 5:38, 8:10
selection box 5:19
sight line 3:5, 5:31, 6:6–6:7
snap priority 5:10
snapping to lines or points 3:1
spacer height 3:5, 5:31
step size 3:1, 3:12, 4:2, 5:1, 5:17–5:18, 5:20, 5:21,
8:14–8:15, 8:19
sticky distance 3:1, 3:12, 5:7–5:9, 5:10, 5:13, 5:18,
5:20–5:24, 6:10, 8:14, 8:19

T

tape measure average temperature 5:8, 7:15–7:16
temperature at cursor 7:14–7:15
Therm File Options 5:8, 5:14, 5:31, 5:35, 7:3, 7:6, 7:9–
7:10
toolbar 1:3, 3:1–3:3, 3:8–3:9, 3:11, 4:2, 4:4–4:5, 5:10,
5:12–5:13, 5:17, 5:20–5:24, 5:27, 5:31, 5:38, 5:40,
5:47–5:48, 6:1–6:4, 6:16, 7:1, 7:4, 7:16, 8:5–8:6,
8:9–8:10, 8:12–8:13, 8:15, 8:19–8:21, 8:24, 8:26,
8:31–8:32, 8:34–8:35
tracing an underlay 3:1, 5:1, 5:13–5:14, 8:1

U

U-factor 3:8–3:9, 5:31, 5:34, 5:50, 6:1, 6:4–6:6, 7:5,
7:6, 7:8, 7:11–7:13, 7:23, 8:32, 8:34, 8:36
underlay 3:1, 4:3, 5:1–5:6, 5:9, 5:10, 5:13–5:14, 5:16,
8:1, 8:3–8:5, 8:7–8:9, 8:12, 8:22

V

vertex 5:13, 5:17, 5:46
View/Crosshair 5:9

View/Material Colors 5:12
View/Set Draw Color 5:12
View/Show Voids/Overlaps 5:3, 5:6, 5:7, 5:11
view-factor radiation model 1:3, 3:10
view-factor smoothing 7:6
voids 3:2, 5:3, 5:6, 5:7, 5:11, 5:14, 6:1–6:2, 6:8, 6:12,
8:25

Z

zoom 3:1–3:2, 3:11, 4:3, 5:4, 5:7–5:8, 5:10, 5:22–5:23,
5:37, 6:10, 8:5, 8:9, 8:12, 8:19, 8:26, 8:30